

OXFORD DIOCESAN ADVISORY COMMITTEE FOR THE CARE OF CHURCHES

MINUTES 8th November 10am

1. Welcome

- 2. Apologies Helen Ensor, James Mackintosh, Ven Jonathan Chaffey, Revd Canon David Tyler
- 3. Minutes of Meeting held on 13th September 2021 The Minutes were approved
- 4. Declarations of Interest None

5. Correspondence, policy and other matters for consideration

- Catriona Turnbull resignation
- 2023 Dates day and time to remain the same
- Christmas gathering (after Evensong)- Thurs 16th December, 7-9pm, McKenna Room, Christ Church, for nibbles and mulled wine.

6. Applications submitted to the DAC since the last agenda

August 2021 – Total: 84						
List B	Faculty DA	Faculty Minor	Faculty Major	Interim/PP/	Early stage	
				Variation	Enquiry	
30	8	12	6	3	25	

September 2021 – Total: 97						
List B Faculty DA Faculty Minor Faculty Major Interim/PP/ Early stage						
				Variation	Enquiry	
29	8	20	10	5	25	

7. Returning Casework

Parish	Dedication					
Steeple Aston	St Peter an	d St Paul				
Application Reference	Archdeaco	nry	Listing	Case Type	Case Officer	
July 2021 documents on <u>dropbox</u> , earlier documents on the <u>OFS</u>	Dorchester		11*	Reordering	LK	
Proposal						
the building. Introductio chancel screen, disposal accessibility, installation external doors to south heating underneath, new disposal of Lady Chapel Significance of fabric	of chancel f of bespoke porch, repla w flooring ar altar, alterat	urniture except the P storage and welcome cement of the timber nd under floor heating	lowman kneelers, area furniture, in pew platforms w within the chanc nd creation of me	alterations to en Istallation of new ith stone floor wit el, installation of	able greater internal and th under floor raised dais,	
affected						
TimelineJul 2015 – Archdeacon Judy visited the church to discuss proposals Sep 2015 – designs received by DAC Nov 2015 – DAC delegation visited Jan 2016 – discussed at DAC meeting Spring 2016 – revised submission sent to DAC? Oct 2016 – revised designs received by DAC? ??Aug 2017 – revised designs received by DAC Aug 2017 – DAC delegation visited Apr 2018 – revised designs received by DAC May 2018 – discussed at DAC meeting and feedback issued Nov 2019 – DAC Chair, Archdeacon, Incumbent, Architect and DAC officers meeting at Church House to discuss way forward Jan 2020 – LK, Archdeacon and Bishop Colin attend PCC meeting at the churd Jul 2021 – revised designs received by DAC, Sept agenda full, on Nov 21 ager					C officers at the church Nov 21 agenda	
Statutory Consultees		Project architect/pro involved	ofessionals	Reviewing DAC N	Vembers	
Historic England	Yes	Kelvin Sampson, Lear	o Architects	Derek Witchell, J Williams, Archde		
CBC	Yes	-		Dorchester, Julia		
SPAB	Yes	-				
Victorian Society	Yes					
Georgian Group	ian Group No					

AMS	No
20 th Century Society	No
LPA (PP)	Yes
LPA (Sch 2)	Yes
BIOS	No
MBS	No
Natural England	No
Minutes of Previous DAC M	eeting:

November 21 Minute:

The DAC felt that there was insufficient justification for the removal of the chancel furniture and, in addition, it should be inspected by DAC members Julian Munby and Abigail Lloyd on site to determine its condition and significance further. The DAC also noted that forming the ramp perpendicular to the dais would enable to it work more cohesively within the design of the dais. In addition, it appears it may be shown too short to meet design standards and The Revd Katie Tupling, the diocesan disability advisor, offered to visit to discuss the design of the ramp not the ramp with the architect on site. It was noted that no designs for the fixing of the retained existing south door, or tower arch screen have been supplied to the DAC.

At this stage, the DAC resolved that a Notification of advice would likely be divided into elements to which it recommended, those it did not object to, and those it objected to. The SCBO to produce a full report for agreement by the DAC either via email or at a future meeting of the DAC Committee.

Parish	Dedication							
Littleworth	Holy Ascen	oly Ascension						
Application Reference	Archdeacor	chdeaconry Listing Case Type Case Officer						
2021-063405	Dorchester		11	Liturgical	AF			
Proposal			<u>-</u>					
advice provided by Suelle Significance of fabric	Introduction of a cross stitch tapestry wall hanging 1m x 1.5m depicting the Ascension of Christ. Design and advice provided by Suellen Pedley, the DAC's textile advisor Significance of fabric Low							
affected Timeline								
Statutory Consultees Project architect/professionals Reviewing DAC Members involved					C Members			
Historic England	No	NA		NA				
СВС	No]						

Victorian Society No Georgian Group No AMS No
AMS No
a a tha a state
20 th Century Society No
LPA (PP) No
LPA (Sch 2) No
BIOS No
MBS No
Natural England No

November 21 Minute:

The committee felt that the revised design of native British Butterflies lacked the required spirituality for such a piece and that certain areas of the design, in particular the size of the butterflies were disproportionate with other elements in the tapestry. It was suggested that the Incumbent be more closely involved with the design of the tapestry to assist with the theological themes and decided this case would be delegated to a subcommittee, to include Archdeacon Judy and The Revd Val Plumb to assist the parish in moving forward with the project.

8. Pre-application or technical site visits to note (06.09.21-08.11.21)

06.09.21 Ewelme reordering (SH)
08.09.21 Binfield All Saints – removal of pews (SH)
14.09.21 Hampstead Norreys – reordering (Peter Preston and Jeff West)
11.10.21 Little Linford St Leonard – new facilities (SH)
14.10.21 Combe Longa St Laurence – removal of organ and West end alterations (SH)
21.10.21 Headington St Andrew – two new stained-glass windows
21.10.21 Dunton St Martin – play area (SH)
01.11.21 Watlington reordering (JS)
04.11.21 Oving new facilities (SH)

9. New Cases

Parish	Dedication			
Headington	St Andrew			
Application Reference	Archdeaconry	Listing	Case Type	Case Officer
2021-061861	Oxford	*	Liturgical	JS

Proposal							
Installation of two stained g	glass wind	lows to designs by Nicholas Mynheer	in the north aisle of the church				
Significance of fabric affected	Low-moderate						
	 15.03.21 – first approach from parish 03.06.21 – Statements received 21.09.21 – Application submitted 24.09.21 – Designs sent to subcommittee and consultees for review 19.10.21 – DAC officer site visit 21.10.21 – Subcommittee site visit 						
Statutory Consultees		Project architect/professionals involved	Reviewing DAC Members				
Historic England	Yes	Nicholas Mynheer	Derek Witchell, Jeff West, Peter				
CBC	Yes		Groves, Sarah Brown, Charlotte Robinson				
SPAB	Yes						
Victorian Society	Yes						
Georgian Group	N/A						
AMS	Yes						
20 th Century Society	N/A						
LPA (PP)	Yes						
LPA (Sch 2)	No						
BIOS	N/A						
MBS	N/A	-					
Natural England	N/A						

November 2021 minute:

The DAC resolved that a *Recommend* NOA should be issued following agreement by the subcommittee of the following design details:

- Further details of how the windows will be fabricated, framed or provided with structural support within the window openings. This should include details of the size and divisions of the glazed components and how they will be offered up to the masonry.
- If fused glass is proposed, the thermal compatibility of the different glasses used should be confirmed to ensure the success and longevity of the artwork.
- Additional information concerning fabricators and materials to be used to be agreed by the DAC stained glass adviser.

Parish	Dedication							
Dunton	St Martir	St Martin						
Application Reference	Archdead	conry	Case Type	Case Officer				
Offline	Buckingh	amshire	*	Churchyard	SH			
Proposal			<u> </u>					
Creation of Play Area in	ı redundar	t area of Churchyard- e	arly stage requ	uest for committee	e's view			
Significance of fabric affected		iyard: Low-moderate g of building: Moderate						
Timeline	involve 09.08.2 possib 21.10.2	09.08.21 Parish contact David Mason, who advises on lease procedure, DAC involvement, and recommends contact with Diocesan Registry and DAC. 09.08.21 PCC begins consultation with DAC and with Diocesan Registry about possibility of leasing an area of churchyard to Parish Council. 21.10.21 SH visits to assess the site, and sends follow-up advice as to process options						
Chattana Crass II.								
Statutory Consultees		Project architect/pro involved	ofessionals	Reviewing DA	C Members			
-	Yes	-	ofessionals	Reviewing DA N/A at present				
Historic England	Yes No	involved	ofessionals					
Historic England CBC		involved	ofessionals					
Historic England CBC SPAB	No	involved	ofessionals					
Historic England CBC SPAB Victorian Society	No Yes	involved	ofessionals					
Historic England CBC SPAB Victorian Society Georgian Group	No Yes No	involved	ofessionals					
Historic England CBC SPAB Victorian Society Georgian Group AMS	No Yes No No	involved	ofessionals					
Historic England CBC SPAB Victorian Society Georgian Group AMS 20 th Century Society	No Yes No No	involved	ofessionals					
Historic England CBC SPAB Victorian Society Georgian Group AMS 20 th Century Society LPA (PP)	No Yes No No No	involved	ofessionals					
Statutory Consultees Historic England CBC SPAB Victorian Society Georgian Group AMS 20 th Century Society LPA (PP) LPA (Sch 2) BIOS	No Yes No No No Yes	involved	ofessionals					
Historic England CBC SPAB Victorian Society Georgian Group AMS 20 th Century Society LPA (PP) LPA (Sch 2)	No Yes No No No Yes No	involved	ofessionals					

November 2021 Minute:

The committee had no objection to the principle of the play area, but on the proviso that the village community is supportive of the churchyard location proposed. Before the PCC goes further, the committee recommended that consultation take place with the wider community specifically over the proposed siting of the play area, since there may be some for whom the siting of a play area within a burial ground is a very sensitive issue, and so careful and considerate engagement will be needed. Other practical suggestions/queries from the committee members were as follows:

- The PCC would need to check who would have insurance liability for the play area, as well as the obligation to maintain the area. The committee felt it ought not to be the PCC's responsibility but that this may be agreed as part of the terms of any lease. Similarly, the formation and maintenance of a path to the area also raises this question.
- Robust but in-keeping fencing is recommended for security for the play area.
- The PCC will want to consider the fixing requirements of the equipment in relation to the possibility of burial archaeology and provide details of this as and when a design is drawn up.
- The safety of the trees in the churchyard, as well as memorial stones, ought to be assessed as part of further preparatory work for this project.
- The PCC will want to consult the LPA, if and when the community is happy with the location proposed.

Parish	Dedication							
Grendon Underwood	St Leonard	St Leonard						
Application Reference	Archdeaco	nry	Listing	Case Type	Case Officer			
2021-063356	Buckingha	Buckinghamshire		Liturgical	SH			
Proposal			I		L			
Installation of piece of s	stained-glas	s for window and woo	den cross to co	mmemorate nev	v roof			
Significance of fabric affected	Low	Low						
Timeline	09.21 S⊦	07.21 Parish submits application 09.21 SH sends to subcommittee 18.10.21 SH emails subcommittee's advice to parish						
Statutory Consultees		Project architect/professionals Re involved		Reviewing DA	AC Members			
Historic England	N/A	N/A		Val Plumb				
СВС	N/A			Derek Witche	11			
SPAB	N/A							
Victorian Society	N/A							
Georgian Group	N/A							
AMS	N/A							
20 th Century Society	N/A							
LPA (PP)	N/A							

LPA (Sch 2)	N/A
BIOS	N/A
MBS	N/A
Natural England	N/A

November 2021 Minute:

While the committee commended the creation of a wooden cross from the roof timbers as a fitting commemoration of the roof repairs, it questioned both the necessity and the appropriateness of an additional tribute in the form of the stained glass panel. While the principle of the stained glass installation is uncontentious and the piece itself is small, the eye will be drawn to it, and the committee was concerned that the design, and in particular, the style in which the church family is depicted, is not of a quality befitting a Grade II* listed building. It was commented that the plain leaded light windows are pleasing as they are, and the committee recommended the parish omit this aspect of the application. The committee agreed to recommend the wooden cross aspect of the proposal, subject to the omission of the stained glass panel.

Parish	Dedication	edication					
Hinton Waldrist	St Margare	Margaret					
Application Reference	Archdeacor	nry	Listing	Case Type	Case Officer		
<u>2021-066113</u>	Dorchester		*	Reordering	LK		
Proposal			I	1	1		
Internal re-ordering to in storage and accessibility and raising of internal flo	alterations.	Installation of west g	allery and relocat	ion of font. Regra			
Significance of fabric affected	Moderat	Moderate					
Timeline	11.03.21 09.06.21 15.06.21 05.10.21	 28.01.21 – initial enquiry from parish 11.03.21 – zoom discussion with DAC officers and parish 09.06.21 – initial documents from parish 15.06.21 – delegation DAC visit 05.10.21 – submission from parish 11.10.21 – LK issues scheme to DAC, amenity societies and LPA (no responses yet received) 					
Statutory Consultees	Project architect/professionals Reviewing DAC Members involved			Vembers			
Historic England	Yes	Christian Randall		Jeff West, James David Tyler	Mackintosh,		
СВС	Yes						
SPAB	Yes						

Yes
No
No
No
No
Yes
No
No

November 21 Minute:

The DAC resolved to support the principle of the alterations, and the option preferred by the parish, feeling that evidence of the stated need had been provided for the facilities and the likely impact on the significance of the church was justified by the benefit the facilities would provide. A query was raised about the handling of the door in the west wall at high level. The feedback letter to be amended to raise this.

Parish	CoE Archdeaconry	Listing	Application Ref	App type	Case type	Works	Status
Ascot Heath: All Saints	BERKSHIRE	Grade II	offline	Enquiry - email	R&C	Door lock - retrospective	Enquiry resolved
Long Crendon: St Mary the Virgin HAR	BUCKINGHAM	Grade I	offline	Enquiry - email	Heating	Boiler breakdown	List A item
Fritwell: St Olave	DORCHESTER	Grade II*	2021- 061699	Faculty - DA	H&S improvements	Safety nets to catch falling plaster	Faculty issued
Stanton Harcourt: St Michael	DORCHESTER	Grade I	2021- 066249	Faculty - DA	Heritage Crime	Window repairs following break-in - RETROSPECTIVE	NOA issued
Little Kimble: All Saints PARISH CONSIDERING CLOSURE	BUCKINGHAM	Grade I	offline	Faculty - DA	PP & M	Memorial outside regs - Malone	NOA issued
Eton: St John the Evangelist	BUCKINGHAM	Grade II	2021- 065329	Faculty - DA	Disposal of items	Disposal of communion silver	Faculty issued
Middleton Stoney: All Saints	DORCHESTER	Grade II*	2018- 028218 and 2018- 028629	Faculty - Major	Development	New toilet and kitchenette at the West end	NOA issued with provisos
Witney: St Mary the Virgin HAR MAJOR PARISH CHURCH	DORCHESTER	Grade I	2021- 061096	Faculty - Major	Liturgical	Icon proposal	Faculty issued
Shipton-on- Cherwell: Holy Cross	DORCHESTER	Grade II	2020- 048636	Faculty - Major	Development	Installation of WC and water supply	NOA issued with provisos

10. List Bs and Notifications of Advice issued under sub-committees and delegated authority since last meeting

Wokingham: St			2021-	Faculty -		Commissioning	Registrar to
Paul	BERKSHIRE	Grade II*	064973	Major	Liturgical	icon	issue faculty
				, í	Ŭ	installation of toilet	,
						in vestry and	
						kitchenette in	
						meeting room and	
Ludgershall: St			2020-	Faculty -		internal plaster	Resolving
	DUCKINCUANA	Cradal	052256		New facilities		0
Mary the Virgin	BUCKINGHAM	Grade I	052250	Major	New facilities	repairs	provisos
						Removal of pews,	
						3x frontals, and old	
						lady chapel altar,	Petition
Marlow: All			2021-	Faculty -		replacement with	submitted to
Saints BUCKING	BUCKINGHAM	Grade II*	064149	Major	Development	chairs	Dio Reg
						recovering the roof	
						and associated	
						drainage and	
						flashing renewal,	
						repairs to the	
						dormers and	
Wheatfield: St			2020-	Faculty -		remedial works to	NOA issued
Andrew	DORCHESTER	Grade I	050747	Minor	R&C	the facade	with proviso
Horspath: St	DOMONEOTEN	Grader	2021-	Faculty -		Replacement	With provise.
Giles	DORCHESTER	Grade II*	062389	Minor	R&C	crosses	NOA issued
Glies	DORCHESTER	Gladell	002389	WIIIO	nac		NOA ISSUEU
Motorete els Ct			2021	For a subtract		Phase 2 of	
Waterstock: St	DODOUSCES	C 1 11*	2021-	Faculty -	59.0	structural repairs to	
Leonard	DORCHESTER	Grade II*	061955	Minor	R&C	chancel	NOA issued
						Repair of bulging	
Swalcliffe: St			2021-	Faculty -		section of	Faculty
Peter & St Paul	DORCHESTER	Grade I	065400	Minor	Churchyard	boundary wall	issued
Fyfield: St			2018-	Faculty -		Churchyard tool	Registrar to
, Nicholas	DORCHESTER	Grade II*	028483	Minor	Churchyard	, store installation.	issue faculty
						Churchyard Gulley	
						Repairs &	
Fyfield: St			2018-	Faculty -		Soakaway	Registrar to
Nicholas	DORCHESTER	Grade II*	028524	Minor	Churchyard	Reinstatements	issue faculty
INICIOIdS	DORCHESTER	Gladell	028524	WIIIO	Churchyaru		issue faculty
Deading, Llaby			2021-	Faculty		Repairs to statue	NOA issued
Reading: Holy		Currenter II		Faculty -	DR C	damaged during	NOA issued
Trinity	BERKSHIRE	Grade II	065358	Minor	R&C	heating installation	with provisos
Wokingham: St			2021-	Faculty -	Lead	Arson & physical	Faculty
Paul	BERKSHIRE	Grade II*	062554	Minor	theft/vandalism	attack	issued
Ickford: St			2019-	Faculty -		Theft of lead from	Faculty
Nicholas	BUCKINGHAM	Grade I	043063	Minor	Heritage Crime	north roof slope	issued
Upton-cum-							
Chalvey,							
Slough: St Mary							
MAJOR PARISH			2021-	Faculty -		Replacement of	
CHURCH	BUCKINGHAM	Grade II*	065674	Minor	Churchyard	vandalised corpus	NOA issued
Castlethorpe: St	DOCKINGINAN	Graden	005074	ivinioi	charchyara	Repairs and	Northsbucu
Simon & St			2021-	Faculty -		redecoration of	Pogistrar to
		Grada					Registrar to
Jude	BUCKINGHAM	Grade I	062548	Minor	PP & M	Tyrill memorial	issue faculty
Drayton							
Beauchamp: St			2021-	Faculty -		Dropped window	Faculty
Mary the Virgin	BUCKINGHAM	Grade I	065196	Minor	R&C	lintel	issued
Caversfield: St			2021-	1			
Laurence HAR	DORCHESTER	Grade II*	063980	List B	R&C	Window repair	List B issued
Somerton: St			2021-			Urgent roof repairs	
James	DORCHESTER	Grade I	066597	List B	R&C	to Lady Chapel	List B issued
Souldern:							
Annunciation of				1			
			2021-	1			
the Blessed	DODCUSCTER	Cup d - 11*		Lint D	Chunghurser		List D issue !
Virgin Mary	DORCHESTER	Grade II*	059970	List B	Churchyard	Wall repairs	List B issued
Stratton				1			
Audley: St Mary			2021-	1		Repointing south	
& St Edburga	DORCHESTER	Grade I	065395	List B	R&C	aisle wall	List B issued

Great Rollright:	I	1	2021-	1	1	Collapsed boundary	I
St Andrew	DORCHESTER	Grade I	066327	List B	Churchyard	wall	List B issued
Stradew	DOMENLESTER	Grader	000327	LIST D	churchyuru	Replacement roof	LIST D ISSUED
						tiles to north	
Newington: St			2021-			transept and	
Giles	DORCHESTER	Grade I	061865	List B	R&C	render repairs	List B issued
Warborough: St	DOMENESTER	Grader	2021-	LIST D	nac	Conservation &	LIST D ISSUED
Lawrence	DORCHESTER	Grade II*	065173	List B	R&C	remedial repairs	List B issued
Lawrence	DORCHESTER	Grade II	005175	LISUD	Nac	Installing of	LIST D ISSUED
Kidmore End: St						streaming	
John the			2021-			-	
	DORCHESTER	Credell	058274	Lint D	M&E	equipment affixed to walls	List B issued
Baptist Rotherfield	DURCHESTER	Grade II	058274	List B	IVIQE		LIST B ISSUED
			2020				
Peppard: All	DODGUEGTED	Cue de UX	2020-	List D	DR C	Calling Danala	List Discussed
Saints	DORCHESTER	Grade II*	053428	List B	R&C	Ceiling Repair	List B issued
Marston: St	0.450.00		2021-			Permanent fixing of	
Nicholas	OXFORD	Grade I	060897	List B	M&E	wifi router	List B issued
Oxford: St			2021-			Fell Horse Chestnut	
Frideswide	OXFORD	Grade II*	066124	List B	Churchyard	tree	List B issued
Shifford: St			2021-			Replacement of	
Mary	DORCHESTER	Grade II	063576	List B	R&C	RWG	List B issued
Shifford: St			2021-			Exterior wood	
Mary	DORCHESTER	Grade II	063580	List B	R&C	redecoration	List B issued
Shifford: St			2021-			Redecoration of	
Mary	DORCHESTER	Grade II	065315	List B	R&C	interior walls	List B issued
Freeland: St			2021-			Blocked downpipe	
Mary the Virgin	DORCHESTER	Grade II*	066493	List B	R&C	and soakaway	List B issued
Long	DONOREDIEN	Graden	000133	LIST D	nac		LIST D ISSUED
Hanborough:			2021-			Bench in	
Christ Church	DORCHESTER	Ungraded	065548	List B	Churchyard	churchyard	List B issued
Sandford: St	DORCHESTER	Ungraueu	2021-	LISUD	Churchyaru		LIST D ISSUEU
Martin	DORCHESTER	Grade II*	065370	List B	R&C	Repairs to south porch roof	List B issued
	DURCHESTER	Grade II	005370	LISUB	RQL		LIST B ISSUED
Shipton-on-			2024			Felling of ash tree	
Cherwell: Holy	DODGUEGTED	Currenter II	2021-	List D	Characherand	which has become	List Discussed
Cross	DORCHESTER	Grade II	064676	List B	Churchyard	dangerous	List B issued
Steeple Aston:							
St Peter & St			2021-			Remove dangerous	
Paul	DORCHESTER	Grade II:*	066184	List B	Churchyard	tree	List B issued
Drayton: St			2021-				
Peter	DORCHESTER	Ungraded	064888	List B	Church	Trim Yew Trees	List B issued
Marcham: All			2021-			Repointing of lead	
Saints	DORCHESTER	Grade II*	063681	List B	R&C	flashing	List B issued
Marcham: All			2021-			Replacement of	
Saints	DORCHESTER	Grade II*	064928	List B	M&E	boilers	List B issued
Easthampstead:							
St Michael & St							
Mary			2021-				
Magdalene	BERKSHIRE	Grade II	065560	List B	M&E	Interior lighting	List B issued
Burghfield: St			2021-			Livestreaming	
Mary the Virgin	BERKSHIRE	Grade II	065002	List B	M&E	equipment	List B issued
Boyne Hill: All			2021-			Upgrade of sound	
Saints	BERKSHIRE	Grade I	063497	List B	M&E	system	List B issued
						Roof repairs to	
Reading: Holy			2021-			chancel and Lady	
Trinity	BERKSHIRE	Grade II	065402	List B	R&C	Chapel	List B issued
	DENKOIIIILE		000402		nac	Installation of	
						Commonwealth	
Tilohurst, Ct			2021				
Tilehurst: St	DEDKOURS	11	2021-	List D	Churchard	War Grave	Link D in a
George	BERKSHIRE	Ungraded	066012	List B	Churchyard	Commission sign	List B issued
						Commonwealth	
Bear Wood: St			2021-			War Graves	
Catherine	BERKSHIRE	Grade II	065991	List B	Churchyard	Commission sign	List B issued
Sonning: St		Grade II*	2021-		H&S	Fire detection	
-	BERKSHIRE		064414	List B	improvements	system	List B issued

BERKSHIRE	Ungraded	2021- 064980	List B	AV	Internet provision	List B issued
	Ŭ	2021-				
DORCHESTER	Grade I	063815	List B	R&C	QI Repairs	List B issued
					Commonwealth	
		2021-			War Graves	
DORCHESTER	Grade I	065970	List B	Churchyard	Commission Sign	List B issued
				· ·	-	
		2021-			reopening of north	
DORCHESTER	Grade I	065133	List B	R&C	transept pew door	List B issued
					Renewal of north	
					aisle roof lead;	
		2021-			minor masonry and	
DORCHESTER	Grade I	062848	List B	R&C	plaster repairs	List B issued
		2021-			Two new internal	
BUCKINGHAM	Grade I	063409	List B	New facilities	notice boards	List B issued
					Removal of	
					leylandii approx	
		2021-			6oft impeding	
BUCKINGHAM	Grade I	065567	List B	Churchyard	railings, highway	List B issued
			1	í í	Installation of BT	
		2021-	1		line for	
BUCKINGHAM	Grade I	065764	List B	AV		List B issued
	-	2021-			<u> </u>	
BUCKINGHAM	Grade I	064334	List B	Churchyard	Memorial bench	List B issued
		2021-	1	, <u>,</u>		
BUCKINGHAM	Grade II*	062374	List B	R&C	Decoration of door	List B issued
					Tree works -	
		2021-				
BUCKINGHAM	Grade II*		List B	Churchvard		List B issued
		2021-	1			
BUCKINGHAM	Grade II*	063067	List B	Churchvard	Gravevard bench	List B issued
		2021-	1			
BUCKINGHAM	Grade II*	065785	List B	Churchvard	Treework	List B issued
		2021-	1		Pollard large ash	
BUCKINGHAM	Grade I		List B	Churchvard	4	List B issued
	0.0001					2.000 0 1050000
		2021-	1			
BUCKINGHAM	Grade II		List B	Churchvard		List B issued
	5.000 11	500010		Sharonyara	50	1.00 2 100000
	1				Memorial outside	
			Private		Nemonarousne	
BERKSHIRE	Grade II*	offline	Private Petition	PP & M		NOA issued
BERKSHIRE	Grade II*	offline	Private Petition	PP & M	regs - Finney	NOA issued
BERKSHIRE	Grade II*	offline		PP & M	regs - Finney Bell repairs -	NOA issued
BERKSHIRE	Grade II*	offline		PP & M	regs - Finney Bell repairs - variation to not use	NOA issued
BERKSHIRE	Grade II*	offline		PP & M	regs - Finney Bell repairs - variation to not use treble in the ring	NOA issued
BERKSHIRE	Grade II*	offline		PP & M	regs - Finney Bell repairs - variation to not use treble in the ring but to relocate	NOA issued
BERKSHIRE	Grade II*	offline		PP & M	regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the	
BERKSHIRE	Grade II*			PP & M	regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and	Awaiting
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd	Awaiting Diocesan
BERKSHIRE	Grade II* Grade I			PP & M OBC	regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble	Awaiting
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble south door too	Awaiting Diocesan
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble south door too damaged to repair	Awaiting Diocesan
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble south door too damaged to repair and use in	Awaiting Diocesan
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble south door too damaged to repair and use in extension, so parish	Awaiting Diocesan
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble south door too damaged to repair and use in extension, so parish wish to fix to	Awaiting Diocesan
		2019-	Petition		regs - Finney Bell repairs - variation to not use treble in the ring but to relocate elsewhere in the church and introduce new 2nd hand treble south door too damaged to repair and use in extension, so parish	Awaiting Diocesan
	DORCHESTER DORCHESTER DORCHESTER DORCHESTER BUCKINGHAM BUCKINGHAM BUCKINGHAM BUCKINGHAM BUCKINGHAM	DORCHESTER Grade I BUCKINGHAM Grade II* BUCKINGHAM Grade II*	DORCHESTERGrade I2021- 063815DORCHESTERGrade I2021- 065970DORCHESTERGrade I2021- 065133DORCHESTERGrade I2021- 062848DORCHESTERGrade I2021- 063409DORCHESTERGrade I2021- 063409BUCKINGHAMGrade I2021- 065567BUCKINGHAMGrade I2021- 065567BUCKINGHAMGrade I2021- 065764BUCKINGHAMGrade I2021- 062374BUCKINGHAMGrade II*2021- 062374BUCKINGHAMGrade II*2021- 062385BUCKINGHAMGrade II*2021- 063067BUCKINGHAMGrade II*2021- 063785BUCKINGHAMGrade II*2021- 061245	BERKSHIREUngraded064980List BDORCHESTERGrade I2021- 063815List BDORCHESTERGrade I2021- 065970List BDORCHESTERGrade I2021- 065133List BDORCHESTERGrade I2021- 062848List BDORCHESTERGrade I2021- 062848List BBUCKINGHAMGrade I2021- 063409List BBUCKINGHAMGrade I2021- 065567List BBUCKINGHAMGrade I2021- 065764List BBUCKINGHAMGrade I2021- 065764List BBUCKINGHAMGrade I2021- 065764List BBUCKINGHAMGrade II*2021- 062374List BBUCKINGHAMGrade II*2021- 062374List BBUCKINGHAMGrade II*2021- 062374List BBUCKINGHAMGrade II*2021- 063067List BBUCKINGHAMGrade II*2021- 063067List BBUCKINGHAMGrade II*2021- 063067List BBUCKINGHAMGrade II*2021- 065785List BBUCKINGHAMGrade II*2021- 065785List BBUCKINGHAMGrade II2021- 061245List BBUCKINGHAMGrade II2021- 061245List BBUCKINGHAMGrade II2021- 061245List BBUCKINGHAMGrade II2021- 061245List B	BERKSHIREUngraded064980List BAVDORCHESTERGrade I063815List BR&CDORCHESTERGrade I2021- 065970List BChurchyardDORCHESTERGrade I2021- 065133List BR&CDORCHESTERGrade I2021- 065133List BR&CDORCHESTERGrade I2021- 0652848List BR&CDORCHESTERGrade I2021- 062848List BR&CBUCKINGHAMGrade I2021- 065567List BNew facilitiesBUCKINGHAMGrade I2021- 065764List BAVBUCKINGHAMGrade I2021- 065764List BAVBUCKINGHAMGrade II064334List BChurchyardBUCKINGHAMGrade III062374List BR&CBUCKINGHAMGrade II*2021- 062385List BChurchyardBUCKINGHAMGrade II*2021- 0663067List BChurchyardBUCKINGHAMGrade II*2021- 063067List BChurchyardBUCKINGHAMGrade II*2021- 065785List BChurchyardBUCKINGHAMGrade II*2021- 065785List BChurchyardBUCKINGHAMGrade II*2021- 065010List BChurchyardBUCKINGHAMGrade II*2021- 065010List BChurchyardBUCKINGHAMGrade II*2021- 065010List BChurchyard	BERKSHIRE Ungraded 064980 List B AV Internet provision DORCHESTER Grade I 063815 List B R&C QI Repairs DORCHESTER Grade I 065970 List B Churchyard Commonwealth War Graves DORCHESTER Grade I 065970 List B Churchyard Plaster repairs & reopening of north DORCHESTER Grade I 065133 List B R&C Plaster repairs & reopening of north DORCHESTER Grade I 065133 List B R&C plaster repairs DORCHESTER Grade I 065133 List B R&C plaster repairs DORCHESTER Grade I 065133 List B R&C plaster repairs BUCKINGHAM Grade I 063409 List B New facilities notice boards BUCKINGHAM Grade I 065567 List B Churchyard Installation of BT line for BUCKINGHAM Grade I 065764 List B AV livestreaming BUCKINGHAM

11. Completed projects feedback

- Boyne Hill All Saints relaying of Victorian floor tiles in original pattern
- Stoke Mandeville St Mary's Roman statue head found in excavations
- Watlington St Leonard completed extension